

AIGHTON, BAILEY & CHAIGLEY PARISH COUNCIL

Pendleview, Lambing Clough Lane
Hurst Green
Clitheroe BB7 9QN
Telephone: 07950 367801

Work or Activity Description – maintenance and relocation of SPID (Speed Indicator Device).			
Identified Hazard	Initial Risk Rating		
	High	Medium	Low
<ul style="list-style-type: none"> • Tripping over while moving unit • Personal injury from use of ladder etc • Falling off ladder while moving unit to another location or replacing battery • Falling into road while working on unit • Falling into hedges etc while working on unit 		x x x	x x
Resulting Harm	Persons at Risk		
<ul style="list-style-type: none"> • Minor personal injuries such as sprained ankles, abrasions, cut fingers etc • Injuries sustained falling off ladder such as broken limbs. • Injuries from bodily contact with moving vehicles 	<ul style="list-style-type: none"> • All users 		
<p>CONTROL MEASURES:</p> <ol style="list-style-type: none"> 1. Ensure area in vicinity of SPID location is free from debris and is safe for ladder use. 2. All equipment including ladders to be checked at regular intervals to ensure safely and properly maintained. Only approved ladders (LCC Highways Training manual) to be used. 3. All users to wear the appropriate PPE at all times when using the equipment or moving the unit from location to location. PPE to include high visibility jacket, sturdy footwear, other appropriate clothing to protect body from abrasions etc while on ladder or near hedging etc. 4. Persons replacing batteries or moving equipment to have received training in these activities. (Training carried out by LCC Highways Dept, Summer, 2013) 5. All equipment, if not in use, to be stored safely. 6. The SPID support poles and plates to be inspected regularly and any defects to be reported to LCC Highways. <p>Updated 16.9.24</p>			

Residual Risk remaining: LOW

Reviewed 16.9.24 Minute 9

ABC Parish Council - Risk Assessments 2019